NACA - LEWIS FLIGHT PROPULSION LABORATORY

INSPECTION - SEPTEMBER 28 - 30, 1948

LIBRARY COPY
RETURN TO
LEWIS LIBRARY
CLEVELAND, OHIO

NACA - LEWIS FLIGHT PROPULSION LABORATORY INSPECTION
September 28 - 30, 1948

TABLE OF CONTENTS

Program Schedule
Opening Remarks
Turbine Cooling Research
Centrifugal Compressor Research
Subsonic Axial - Flow Compressor Research
Supersonic Compressor
Combustion Research
Fuels Research
Stress and Vibration
Materials Demonstration
Engine Controls Research
Turbojet Research
Ram - Jet Research
Supersonic Boundary Layer Measurement Techniques
Supersonic Tunnel
Press Release

DRAFT of September 2, 1948

NATIONAL ADVISORY COMMITTEE FOR AERONAUTICS

PROGRAM

Renaming the Cleveland Laboratory
September 28, 1948

Chairman Hunsaker
Master of Ceremonies

1. The Chairman welcomes the audience, establishes the atmosphere for the ceremonies by reviewing the circumstances under which the Committee learned of Dr. Lewis' death, calls upon the Executive Secretary to read extract from the minutes, etc.

2. Executive Secretary reads the extract from the minutes of the previous meeting at which it was decided to rename the laboratory in honor of Dr. Lewis, and as first employee of the Committee, expresses to the members of the Committee on behalf of the employees in all laboratories of the NACA the thanks of the entire staff for having thus honored their former beloved leader.

3. Vice Admiral Emory S. Land, USN (Ret.), is introduced as former member of NACA. He speaks on the significance of Lewis' life work to the advancement of aeronautical science, etc.

4. The Chairman formally renames the laboratory the LEWIS FLIGHT PROPULSION LABORATORY and pulls the drawstrings which unveil a plaque, which he presents to Dr. Sharp, Director of the laboratory.

5. Dr. Sharp responds briefly.

Admiral King speaks briefly

1948 INSPECTION

LEWIS FLIGHT PROPULSION LABORATORY

NACA CLEVELAND

September 28, 1948

Eastern Standard Time	
8:30 am	Busses leave Cleveland Hotel for Laboratory
9:10	Registration in lobby of Administration Building; baggage checked in Room 111.
9:30	Lewis Commemoration Ceremonies. Opening session for 1948 inspection
10:30	Inspection of Laboratory in 8 groups designated by colors

	RED	WHITE	BLUE	GREEN	BROWN	GOLD	BUFF	YELLOW
Turbine Research W-5, W-7 Eng. Res. Bldg.	* 10:40 am	4:10 pm	3:35 pm	3:00 pm	‖ 2:25 pm	12:25 pm	11:50 am	11:15 am
Compressor Research W-2 Eng. Res. Bldg.	11:15	* 10:40 am	4:10	3:35	3:00	‖ 2:25	12:25 pm	11:50
Combustion Research CW-5, SW-21, Eng. Res. Bldg.	11:50	11:15	* 10:40 am	4:10	3:35	3:00	‖ 2:25	12:25 pm
Fuels Research Fuels & Lubricants Bldg. Jet Propulsion Fuels Bldg.	12:25 pm	11:50	11:15	* 10:40 am	4:10	3:35	3:00	‖ 2:25
Supersonic Research 8- by -6-Foot Supersonic Wind Tunnel	‖ 2:25	12:25 pm	11:50	11:15	* 10:40 am	4:10	3:35	3:00
Materials & Stresses Research J.P. Static Lab.	3:00	‖ 2:25	12:25 pm	11:50	11:15	* 10:40 am	4:10	3:35
Controls Research Propeller Res. Bldg.	3:35	3:00	‖ 2:25	12:25 pm	11:50	11:15	* 10:40 am	4:10
Turbojet Engine Research Altitude Wind Tunnel	4:10	3:35	3:00	‖ 2:25	12:25 pm	11:50	11:15	* 10:40 am

Luncheon in Auditorium at 1:00 pm.

Busses leave for Downtown Cleveland at 4:45 pm.

*Start
‖Luncheon

1948 INSPECTION

LEWIS FLIGHT PROPULSION LABORATORY

NACA CLEVELAND

September 29 and 30, 1948

Eastern Standard Time	
8:30 am	Busses leave Cleveland Hotel for Laboratory
9:10	Registration in lobby of Administration Building; baggage checked in Room 111
9:30	Opening session for 1948 inspection
10:00	Inspection of Laboratory in groups designated by colors

	RED	WHITE	BLUE	GREEN	BROWN	GOLD	BUFF	YELLOW
Turbine Research W-5, W-7 Eng. Res. Bldg.	*10:10 am	3:50 pm	3:15 pm	‖ 2:40 pm	12:30 pm	11:55 am	11:20 am	10:45 am
Compressor Research W-2 Eng. Res. Bldg.	10:45	*10:10 am	3:50	3:15	‖ 2:40	12:30 pm	11:55	11:20
Combustion Research CW-5,SW-21, Eng. Res. Bldg.	11:20	10:45	*10:10 am	3:50	3:15	‖ 2:40	12:30 pm	11:55
Fuels Research Fuels & Lubricants Bldg. Jet Propulsion Fuels Bldg.	11:55	11:20	10:45	*10:10 am	3:50	3:15	‖ 2:40	12:30 pm
Supersonic Research 8- by -6-Foot Supersonic Wind Tunnel	12:30 pm	11:55	11:20	10:45	*10:10 am	3:50	3:15	‖ 2:40
Materials & Stresses Research J.P. Static Lab.	‖ 2:40	12:30 pm	11:55	11:20	10:45	*10:10 am	3:50	3:15
Controls Research Propeller Res. Bldg.	3:15	‖ 2:40	12:30 pm	11:55	11:20	10:45	*10:10 am	3:50
Turbojet Engine Research Altitude Wind Tunnel	3:50	3:15	‖ 2:40	12:30 pm	11:55	11:20	10:45	*10:10 am

‖ Luncheon in Auditorium 1:05 pm.

Busses leave for Downtown Cleveland 4:25 pm.

*Start
‖Luncheon